



New Ultra Gas Heat Exchanger Replacement Kits

Our Ultra Gas heat exchanger replacement kits have changed to span all Series of Ultras (S1-S4), to better align with warranty coverage terms and to reduce pricing. The existing heat exchanger replacement kit part numbers are now discontinued and replaced with new kit part numbers. The main differences between the discontinued and new kit contents are the removal of the Sentinel X100 inhibitor product, the heat exchanger cover plate and burner - all of which are still available as separate part numbers in the respective Boiler Manual. For a complete content listing of the new heat exchanger replacement kits for Ultra Series 1-4 boilers, please click on the link below.

[Click Here - New Heat Exchanger Replacement Instructions](#)

The chart below identifies the Ultra Gas heat exchanger replacement kit part numbers, and new lower prices.

SIZE	DISCONTINUED PART #s	NEW PART #s
Ultra 80 NG	383-500-670	383-500-773
Ultra 80 LP	383-500-671	
Ultra 105	383-500-672	383-500-774
Ultra 155	383-500-673	383-500-775
Ultra 230	383-500-674	383-500-776
Ultra 299/399	383-500-675	383-500-777

If you have any questions regarding kit contents, please call our Weil-McLain Technical Services Department at 1-800-654-2109 (option 2), or email wmttechnicalservices@weil-mclain.com.

